

2013 Honda Brio

VX (O) AT

Rs 4,40,000



29020 KM



petrol



automatic



grey



MG Road, Gurgaon

Registration Year: Jul 2013
RTO: Faridabad

Make Year: Jul 2013
Owners: 1

Insurance: Comprehensive (Jul. 2017)
Reason for sale: Not in use



LEFT FRONT CORNER VIEW



LEFT SIDE VIEW



LEFT REAR CORNER VIEW



BACK VIEW



FRONT VIEW



ENGINE & BONNET OPEN FRONT VIEW



CLUSTERMETER VIEW



DASHBOARD VIEW

Introducing Spinny Assured

Our Promise of Complete Happiness & Satisfaction with Every Spinny Assured Car



5 Days
Money Back
Guarantee

200 PTS
Quality
Inspection
Check

1 Year
Service
Warranty

Car inspection report




Interiors

- Central locking system is working fine
- Upholstery is in good condition
- Roof lining is in good condition
- Carpet and floor mats are free of cuts and tears
- All functions in cluster panel are working fine
- AC blower operates as designed



Road Test

- Steering is perfectly aligned
- Power steering operates as designed
- Engine exhibits appropriate power
- Gear shift is operating smoothly
- Shockers have no abnormal noise




Engine Compartment

- Side Members are ok.
- Apron are ok.
- Side Walls are ok.
- Side Walls are ok.
- Car has no white or black smoke
- Engine has no abnormal noise
- Engine has no back compression
- Radiator is in good condition
- Coolant is free of foreign material
- Ignition system is working fine
- Engine starting in single crank
- Battery is in good condition
- Steering system working properly
- Alternator belt is working smoothly
- Wiper working smoothly
- AC compressor is working smoothly



Exterior

- There is dent on Left running board
- Rear right door are repaired
- No corrosion in body panels
- Rear right door have been replaced
- No body parts have cracks
- No cracks in rims and alloys
- No dents in rims and alloys
- No repair in pillars
- Turn signal lights working fine
- There is scratch on Rear Bumper and Left running board
- Front Bumper,Front right door,Rear right door,Right Quarter panel,Rear Bumper,Left Quarter panel,Left Front Door and Left fender are Repainted
- Left running board requires paint



Underbody

- Main oil seal has no sign of oil leaks
- Shockers are in good condition



Tyres

Right Front Tyre	30.0%
Left Front Tyre	30.0%
Right Rear Tyre	30.0%
Left Rear Tyre	30.0%
Spare Tyre	30.0%

Pricing

Spinny Price

Rs 4,40,000

Including benefits of Spinny Assured

Market Price

Rs 4,88,870

Save Rs. 48,870 with Spinny

New Car on-road Price

Rs 7,80,640

Save 43.6% with Spinny



For more details visit

myspinny.com

(Search this car by product ID: 6895)



For test drive visit us at

Spinny Car Hub, Plaza Mall

MG Road, Gurgaon

(It is advisable to check availability online)




You can call us on

8010100900

(Search this car by product ID: 6895)

Sell your Car to Spinny for Same Day Cash

And Skip th Hassles of Listings, test Drives & Weeks of Uncertainty



1. Instant Online Quote



2. Free Doorstep Inspection



3. Same Day Payment

[View this product on www.myspinny.com >](http://www.myspinny.com)